



United States Steel Corporation
Clairton Works
400 State Street
Clairton, PA 15025

RECEIVED

APR 10 2009

March 20, 2009

to Protection Division (3AP12)

Mr. James Thompson
Department of Air Quality
Bureau of Air Pollution Control
301 Thirty-Ninth Street
Pittsburgh, PA 15201

U.S. Environmental Protection Agency
Region III
Air, Radiation & Toxics Division
1650 Arch Street
Philadelphia, PA 19103-2029
ATTN: James W. Hagedorn (3AT23)

Assistant Council
Department of Environmental Protection
Southwest Region
400 Waterfront Drive
Pittsburgh, PA 15222-4745
ATTN: Steve Hepler

Department of Justice
Environmental and Natural Resource Division
Environmental Enforcement Section
P.O. Box 7611
Ben Franklin Station
Washington, D.C. 20044
ATTN: David Street, Esq.

Subject: USS Reference Number: 09-0230
ACHD Reference Number: 11190
Sulfur Plant
USS Clairton Works

RECEIVED

APR 1 2009

to Protection Division (3AP12)

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 412-233-1015.

Sincerely,

Mark G. Tabler
Plant Manager
Clairton Works

NOTICE OF OUTAGE OF EQUIPMENT
ARTICLE XXI - SECTION 2108.1

1. **USS Reference Number:** 09-0230
ACHD Reference Number: 11190
2. **Date & Time of Breakdown:** Date: 03/20/09 Time: 0900 hours
3. **Company Name:** U.S. Steel Corporation - USS Clairton Works
4. **Specific Equipment Involved or Affected:** Sulfur Plant
5. **BAPC Permit Number (if applicable):**
6. **Location:** Clairton, PA
7. **Nature and cause of breakdown:** The 101J spare sulfur plant stripper vacuum axi was unavailable for service while the inter-stage valve was replaced. The 101J Axi is a redundant piece of equipment. The spare C658 Axi carried the full load. Sulfur Plant performance was not affected.
8. **Identification of Emissions:**
 - A. **Type(s) (CO, NOX, SO₂, Particulates, Hydrocarbons, etc.)**
The spare C658 Axi carried the full load. No environmental impact is expected.
 - B. **Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality).** N/A No environmental impact is expected.
 - C. **Amount of each type emitted (or likely to be emitted).**
N/A
9. **Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).**
The spare C658 Axi carried the full gas flow to the plant. The repairs were completed.
10. **Facility back in operation -** Date: 03/20/09 Time: 0945 hours

Signature Coleen M. Davis Date 3-24-09
Coleen M. Davis
Senior Environmental Control Engineer Phone: 412-233-1015